


ASSEMBLY INSTRUCTION 52100

①. Table base
2 PCS



②. Connecting board
2 PCS



③. Table top
1 PC




④. Screw
14 PCS
M8x35mm



⑤. Washer
14 PCS
M8xØ18mm




⑥. Allen wrench
1 PC
M5




⑦. Felt pad
12 PCS
Ø50mm






1



2



3



4

