


ASSEMBLY INSTRUCTION 52120

①. Table base
1 PC



②. Connecting board
1 PC



③. Table top
1 PC



④. Screw
7 PCS
M8x35mm



⑤. Washer
7 PCS
M8xØ18mm




⑥. Allen wrench
1 PC
M5




⑦. Felt pad
9 PCS
Ø50mm





1



2




3




10 MIN.

X 2



4



100%