





ASSEMBLY INSTRUCTION 3117

LIST OF ACCESSORIES





A




X16

B



X16

C



X8

D



M5*16

X10

E



M6*35

X8

F



M6*16

X6

G



M6*18


X14

H



X2

I



5#


X1

J




X10


1



2



3



4

